



# Certificate of Registration

This certifies that the Quality Management System of

## Repair Industries of Michigan, Inc. dba RIM Custom Racks

6501 E. McNichols  
Detroit, Michigan, 48212, United States

has been assessed by NSF-ISR and found to be in conformance to the following standard(s):

## ISO 9001:2015

### Scope of Certification:

Container and rack build including prototype, fabrication, modification, repair, salvage, and container components.

A handwritten signature in black ink.

**Sameer Vachani**  
Senior Director, NSF-ISR

**Certificate Number:** 6L911-IS10  
**Certificate Decision Date:** 26-SEP-2025  
**Certificate Issue Date:** 26-SEP-2025  
**Cycle Effective Date:** 14-OCT-2025  
**Certificate Expiration Date\*:** 13-OCT-2028

Issued by:  
**NSF International Strategic Registrations (NSF-ISR)**  
789 N. Dixboro Road, Ann Arbor, MI 48105 USA

Authorized Certification and/or Accreditation Marks. This certificate is property of NSF-ISR and must be returned upon request.

\*Company is audited for conformance at regular intervals. To verify certification call (888) NSF-9000 or visit our web site at [www.nsf-isr.org](http://www.nsf-isr.org)





# Certificate of Registration

## ANNEX PAGE FOR CERTIFICATE NUMBER: 6L911-IS10

*This Annex is only Valid in connection with the above-mentioned certificate issued by NSF-ISR*

**CERTIFICATE ISSUE DATE:**  
26-SEP-2025

**CERTIFICATE EXPIRATION DATE:**  
13-OCT-2028

*Repair Industries of Michigan, Inc. dba RIM  
Custom Racks*

6501 E. McNichols  
Detroit, Michigan, 48212, United States

**Location:**  
Repair Industries of Michigan, Inc  
dba RIM Custom- C0331870  
6475 E. McNichols  
Detroit, Michigan, 48212, United  
States

**Scope:**  
This location is part of site  
6L911. Supporting processes  
include:  
Painting and Coating of racks  
and components

**Location:**  
Repair Industries of Michigan, Inc.  
dba RIM Custom Racks- C0331874  
17315 Sherwood  
Detroit, Michigan, 48212, United  
States

**Scope:**  
This location is part of site  
6L911. Supporting processes  
include:  
Prototype assembly and  
Fixturing

**Location:**  
Repair Industries of Michigan, Inc.  
dba RIM Custom Racks- C0331875  
17341 Sherwood  
Detroit, Michigan, 48212, United  
States

**Scope:**  
This location is part of site  
6L911. Supporting processes  
include:  
Administrative operations and  
sales

**Location:**  
Repair Industries of Michigan, Inc.  
dba RIM Custom Racks- C0331872  
6535 E. McNichols  
Detroit, Michigan, 48212, United  
States

**Scope:**  
This location is part of site  
6L911. Supporting processes  
include:  
Fabrication and machine shop

Issued by:  
**NSF International Strategic Registrations (NSF-ISR)**  
789 N. Dixboro Road, Ann Arbor, MI 48105 USA

Authorized Certification and/or Accreditation Marks. This certificate is property  
of NSF-ISR and must be returned upon request.

*\*Company is audited for conformance at regular intervals. To verify  
certification call (888) NSF-9000 or visit our web site at [www.nsf-isr.org](http://www.nsf-isr.org)*

